

GAS SAFETY RECALL

Swift Appliance Group 500 Series Cooker/Grill and Cooktops

Model Numbers 502BHSP, 502BHFV, 502DHSP, 502RHSP, 502SHFW, 502SHW, 502WBHSP, 503BHSPM, 503BHSP, 503BHSPMLG, 503BHSW, 503DHSP, 503RHSP, 503SHSPM, 503SHSW and 503BHSPN



IDENTIFICATION: The information in this recall advertisement will be updated when more information is available.

Approval Number AGA 6488G - Data plate located on the inside front left side of the lid.

Products supplied to consumers, caravan, camper and motorhome manufacturers between 01/01/2019 and 1/06/2020.

DEFECT: A part of the gas supply pipe may break or develop a hole. This may cause a gas leak.

HAZARD: If the gas leaks in the presence of an ignition source this may lead to an explosion and/or fire, which may result in serious illness, injury or death. The defect has caused incidents that have caused serious injuries and burns.

If gas leaks and builds up in an enclosed area, such as a motorhome or caravan, asphyxiation may occur.

ACTION REQUIRED:

Consumers should check if their appliance is affected and if so immediately turn off the appliance and do not operate it on gas. The gas supply to the appliance can be isolated at the gas isolation valve, adjacent to the appliance.

To identify affected appliances, open the glass lid and check the model number on the data plate that is on the inside front left side of the lid.

Consumers must ensure that Gas Cooker units are serviced and tested every 2-3 years.

For further information, consumers with affected appliances can contact Swift Appliance Group by phone on 0412 821 912 (Monday to Friday 9am to 5pm), via email at swiftrecall@outlook.com or visit <https://www.swiftappliancegroup.com.au> to register their details to be advised of remedial actions when they are available as the remedial process has not yet been finalised.

Version 1 - 22 June 2022

See www.productsafety.gov.au for Australian product recall information